



# Busy Bee

## EFM8BB52 Errata

---



This document contains information on the EFM8BB52 errata. The latest available revision of this device is revision C.

Errata that have been resolved remain documented and can be referenced for previous revisions of this device.

The device data sheet explains how to identify the chip revision, either from the package marking or electronically.

Errata effective date: April, 2023.

## 1. Errata Summary

The table below lists all known errata for the EFM8BB52 and all unresolved errata of the EFM8BB52.

**Table 1.1. Errata Overview**

Designator	Title/Problem	Workaround Exists	Exists on Revision:		
			A	B	C
ADC_E201	Incorrect Output Upon MUX Switch	Yes	X	—	—
BL_E201	UART Bootloader Bootload Mode Entry Pin Not Available	Yes	X	X	X; resolved on devices with date code 2330 and later
CLK_E201	Incorrect SYSCLK Transition Restrictions	Yes	X	—	—
CLU_E201	Incorrect CLU to SPI Connections	Yes	X	—	—
CORE_E201	Prefetch Engine May Get Incorrect Flash Data When Exiting Snooze Mode	Yes	X	—	—
CUR_E201	Excess Current Consumption	No	—	X	—
POR_E201	POR Circuit Does Not Start Up	No	X	—	—
PWR_E201	Wakeup From Shutdown Mode Fails at High VDD and Low Temperatures	No	X	X	—
VREF_E201	RTS Noise Present In Reference Voltage Output	No	X	—	—

## 2. Current Errata Descriptions

This section contains known errata for revision C of this device.

### 2.1 BL\_E201 – UART Bootloader Bootload Mode Entry Pin Not Available

<b>Description of Errata</b>
The data sheet states all devices come pre-programmed with UART bootloader in device flash. The pre-programmed factory bootloader for QFN20 and TSSOP20 packaged EFM8BB52 devices use an unavailable pin for bootload mode entry.
<b>Affected Conditions / Impacts</b>
<p>When bootloader firmware executes on EFM8BB52 devices with QFN20 and TSSOP20 packaging, the unavailable pin used for bootload entry always reads logic low, putting the device in bootload mode. Application firmware can execute <i>after</i> an application firmware upload via bootloader, however following a reset, the device will revert back to bootload mode and will not progress to an uploaded application.</p> <p>The factory bootloader does not work as intended on QFN20 or TSSOP20 packaged EFM8BB52 devices.</p>
<b>Workaround</b>
<p>A bootloader is not required for normal operation. For applications that do not use the bootloader, the Bootloader Signature Byte can be modified to any value other than 0xA5 to enable normal operation. This is most commonly achieved by erasing the code security page in flash, which will also erase the pre-programmed factory bootloader.</p> <p>If a bootloader is required by the application, a custom-written bootloader can be downloaded to the device, replacing the pre-programmed factory bootloader image. A bootloader binary is also provided in <i>AN945: "EFM8 Factory Bootloader User Guide"</i> which utilizes the bootload entry pin specified in the device data sheet, and can be used to replace the factory bootloader.</p>
<b>Resolution</b>
<p>This issue is resolved in revision C devices with date code 2330 and later.</p> <p>More information on the bootloader can be found in the device data sheet and in <i>AN945: "EFM8 Factory Bootloader User Guide"</i>. Application notes can be found on the Silicon Labs website (<a href="http://www.silabs.com/8bit-appnotes">www.silabs.com/8bit-appnotes</a>) and in Simplicity Studio using the [Application Notes] tile.</p>

### 3. Resolved Errata Descriptions

This section contains previous errata for EFM8BB52 devices.

For errata on the latest revision, refer to the beginning of this document. The device data sheet explains how to identify chip revision, either from package marking or electronically.

#### 3.1 ADC\_E201 – Incorrect Output Upon MUX Switch

<b>Description of Errata</b>
Incorrect ADC output can occur when the ADC is always on (i.e. IPOEN = 0) and the channel sequencer switches between certain channels.
<b>Affected Conditions / Impacts</b>
For the 32- and 28-pin packages: When IPOEN = 0 and the sequencer changes from a multiplexer channel $\leq 7$ to a channel $\geq 8$ , the ADC conversion results for channels 8 and higher will be incorrect.
For the 20-pin packages, When IPOEN = 0 and the sequencer changes from a multiplexer channel $\leq 6$ to a channel $\geq 7$ , the ADC conversion results for channels 7 and higher will be incorrect.
<b>Workaround</b>
For the 32- and 28-pin packages:  When using the sequencer with IPOEN = 0, avoid configurations in which the sequencer will change from channel 7 to channel 8. If ADC0MX is $\leq 7$ , then ADC0MX + NASCH must also be $\leq 7$ . The problem is not observed when the ADC powers down between conversions (when IPOEN = 1).
For the 20-pin packages:  When using the sequencer with IPOEN = 0, avoid configurations in which the sequencer will change from channel 6 to channel 7. If ADC0MX is $\leq 6$ , then ADC0MX + NASCH must also be $\leq 6$ . The problem is not observed when the ADC powers down between conversions (when IPOEN = 1).
<b>Resolution</b>
This issue is resolved in revision B devices.

### 3.2 CLK\_E201 – Incorrect SYSCLK Transition Restrictions

<b>Description of Errata</b>
<p>The clock selection logic does not allow switching to the HFOSC0 49 MHz or 49/1.5 MHz output when SYSCLK is currently using an HFOSC0 output and clock divider combination that results in a frequency less than 24.5 MHz. This means that SYSCLK can switch to the HFOSC0:</p> <ul style="list-style-type: none"> <li>• 49 MHz or</li> <li>• 49/1.5 MHz</li> </ul> <p>output only when SYSCLK is already:</p> <ul style="list-style-type: none"> <li>• 49 MHz,</li> <li>• 49/1.5 MHz,</li> <li>• 49 MHz with a 2x divider or</li> <li>• 24.5 MHz.</li> </ul> <p>On revision A devices, the clock selection logic permits SYSCLK to switch to:</p> <ul style="list-style-type: none"> <li>• 49 MHz,</li> <li>• 49/1.5 MHz or</li> <li>• 49 MHz with a 2x divider</li> </ul> <p>only when SYSCLK is already:</p> <ul style="list-style-type: none"> <li>• 49 MHz,</li> <li>• 49/1.5 MHz,</li> <li>• 49 MHz with a 2x divider,</li> <li>• 24.5 MHz,</li> <li>• 49 MHz with a 3x divider or</li> <li>• 49/1.5 MHz with a 2x divider.</li> </ul>
<b>Affected Conditions / Impacts</b>
<p>Switching SYSCLK to the 49MHz (CLKSL = 0x3) HFOSC0 output with a 2x divider (CLKDIV = 0x1) will only work when switching from one of the listed HFOSC0 output and clock divider combinations allowed for revision A.</p> <p>When switching SYSCLK from an HFOSC0 output and clock divider combination that results in a frequency less than 24.5 MHz to 49 MHz or 49/1.5 MHz, the core logic voltage regulator may experience a drop-out condition that potentially causes the device to lock-up. A power-on-reset is required to recover from the lock-up.</p>
<b>Workaround</b>
<p>Before switching SYSCLK to the 49 MHz HFOSC0 output with a 2x divider, first select one of the listed HFOSC0 output and clock divider combinations allowed for revision A.</p> <p>Do not select the 49 MHz or 49/1.5 MHz HFOSC0 output when SYSCLK is currently using an HFOSC0 output and clock divider combination that results in a frequency less than 24.5 MHz. First select one of the listed HFOSC0 output and clock divider combinations that results in a frequency greater than or equal to 24.5 MHz, then select the 49 MHz or 49/1.5 HFOSC0 output.</p>
<b>Resolution</b>
<p>This issue is resolved in revision B devices.</p>

### 3.3 CLU\_E201 – Incorrect CLU to SPI Connections

<b>Description of Errata</b>					
The connections between the CLU <sub>n</sub> outputs and the SPI0 inputs are incorrect.					
<b>Affected Conditions / Impacts</b>					
<p>The CLU<sub>n</sub> to SPI0 connections are incorrect on revision A devices. Specifically, there is no connection between the CLU0 output and SPI0. Connections exist between each of the CLU1, CLU2, and CLU3 outputs and the SPI0 inputs. When using CLU<sub>n</sub> to SPI0 connections, users should be aware that:</p> <ol style="list-style-type: none"> <li>1. The CLU0 output cannot be used as an input to SPI0 on revision A.</li> <li>2. Each output from CLU[3:1] can be used as an input to SPI0 on revision A.</li> <li>3. The fix for the CLU0-to-SPI0 connections on revision B and later will require firmware that configures any CLU[3:1] outputs for use as inputs to SPI0 on revision A devices to be rewritten.</li> </ol>					
<b>Workaround</b>					
<p>User firmware can still assign CLU1, CLU2, and CLU3 outputs to SPI0 input signals as shown below, however the CLU0 output is not available as a SPI0 input. <a href="#">Table 3.1 CLU Output Configuration on page 6</a> shows the connections between CLU<sub>n</sub> and SPI0 in Revision A devices.</p>					
<b>Table 3.1. CLU Output Configuration</b>					
CLU0.OUT	CLU1.OUT	CLU2.OUT	CLU3.OUT	Register Configuration	Output Type
-	SPI MOSI	SPI SCK	SPI MISO	Set via SPI0PCF	Asynchronous
-	SPI MISO	SPI MOSI	SPI SCK		

Table 3.2 SPI0PCF: SPI0 Pin Configuration on page 7 shows the SPI0 input signal configuration options in the SPI0PCF register for Revision A devices.

**Table 3.2. SPI0PCF: SPI0 Pin Configuration**

Bit	7	6	5	4	3	2	1	0
Name	SCKSEL		Reserved	MISEL		Reserved	SISEL	
Access	RW		R	RW		R	RW	
Reset	0x0		0	0x0		0	0x0	

SFR Page = 0x20; SFR Address: 0xDF

Bit	Name	Reset	Access	Description												
7:6	SCKSEL	0x0	RW	<b>Slave Clock Input Select.</b>  This bit selects the source of the SCK clock input signal in slave mode. <table><tr><th>Value</th><th>Name</th><th>Description</th></tr><tr><td>0x0</td><td>CROSSBAR</td><td>SCK (slave mode clock input) is connected to the pin assigned by the crossbar.</td></tr><tr><td>0x1</td><td>CLU2</td><td>SCK (slave mode clock input) is connected to the CLU2 output.</td></tr><tr><td>0x2</td><td>CLU3</td><td>SCK (slave mode clock input) is connected to the CLU3 output.</td></tr></table>	Value	Name	Description	0x0	CROSSBAR	SCK (slave mode clock input) is connected to the pin assigned by the crossbar.	0x1	CLU2	SCK (slave mode clock input) is connected to the CLU2 output.	0x2	CLU3	SCK (slave mode clock input) is connected to the CLU3 output.
Value	Name	Description														
0x0	CROSSBAR	SCK (slave mode clock input) is connected to the pin assigned by the crossbar.														
0x1	CLU2	SCK (slave mode clock input) is connected to the CLU2 output.														
0x2	CLU3	SCK (slave mode clock input) is connected to the CLU3 output.														
5	Reserved	Must write reset value.														
4:3	MISEL	0x0	RW	<b>Master MISO Input Select.</b>  This bit selects the source of the MISO data input signal in master mode. <table><tr><th>Value</th><th>Name</th><th>Description</th></tr><tr><td>0x0</td><td>CROSSBAR</td><td>MISO (master mode data input) is connected to the pin assigned by the crossbar.</td></tr><tr><td>0x1</td><td>CLU1</td><td>MISO (master mode data input) is connected to the CLU1 output.</td></tr><tr><td>0x2</td><td>CLU3</td><td>MISO (master mode data input) is connected to the CLU3 output.</td></tr></table>	Value	Name	Description	0x0	CROSSBAR	MISO (master mode data input) is connected to the pin assigned by the crossbar.	0x1	CLU1	MISO (master mode data input) is connected to the CLU1 output.	0x2	CLU3	MISO (master mode data input) is connected to the CLU3 output.
Value	Name	Description														
0x0	CROSSBAR	MISO (master mode data input) is connected to the pin assigned by the crossbar.														
0x1	CLU1	MISO (master mode data input) is connected to the CLU1 output.														
0x2	CLU3	MISO (master mode data input) is connected to the CLU3 output.														
2	Reserved	Must write reset value.														
1:0	SISEL	0x0	RW	<b>Slave MOSI Input Select.</b>  This bit selects the source of the MOSI data input signal in slave mode. <table><tr><th>Value</th><th>Name</th><th>Description</th></tr><tr><td>0x0</td><td>CROSSBAR</td><td>MOSI (slave mode data input) is connected to the pin assigned by the crossbar.</td></tr><tr><td>0x1</td><td>CLU1</td><td>MOSI (slave mode data input) is connected to the CLU1 output.</td></tr><tr><td>0x2</td><td>CLU2</td><td>MOSI (slave mode data input) is connected to the CLU2 output.</td></tr></table>	Value	Name	Description	0x0	CROSSBAR	MOSI (slave mode data input) is connected to the pin assigned by the crossbar.	0x1	CLU1	MOSI (slave mode data input) is connected to the CLU1 output.	0x2	CLU2	MOSI (slave mode data input) is connected to the CLU2 output.
Value	Name	Description														
0x0	CROSSBAR	MOSI (slave mode data input) is connected to the pin assigned by the crossbar.														
0x1	CLU1	MOSI (slave mode data input) is connected to the CLU1 output.														
0x2	CLU2	MOSI (slave mode data input) is connected to the CLU2 output.														

#### Resolution

This issue is resolved in revision B devices.

### 3.4 CORE\_E201 – Prefetch Engine May Get Incorrect Flash Data When Exiting Snooze Mode

<b>Description of Errata</b>
When the prefetch engine is enabled and the device enters then exists Snooze mode, the prefetch engine may read incorrect data from the flash and propagate it to the instruction register.
<b>Affected Conditions / Impacts</b>
When the prefetch engine is enabled and the device enters then exits Snooze mode, the CPU may receive an invalid instruction, resulting in unexpected behavior.
<b>Workaround</b>
Before entering Snooze mode, ensure that: <ul style="list-style-type: none"> <li>• The SYSCLK is less than 25 MHz</li> <li>• The prefetch engine is disabled by setting PFE0CN.FLRT = 0</li> </ul>
<b>Resolution</b>
This issue is resolved in revision B devices.

### 3.5 CUR\_E201 – Excess Current Consumption

<b>Description of Errata</b>
Current consumption is higher than specified in all power modes except Shutdown mode.
<b>Affected Conditions / Impacts</b>
In any power mode other than Shutdown mode, the device consumes about 100 $\mu$ A excess current at 25 degrees Celsius.
<b>Workaround</b>
There is no workaround for this issue.
<b>Resolution</b>
This issue is resolved in revision C devices.

### 3.6 POR\_E201 – POR Circuit Does Not Start Up

<b>Description of Errata</b>
The POR circuit does not start on about 5% of revision A devices.
<b>Affected Conditions / Impacts</b>
The device cannot enter Shutdown mode. If Shutdown mode is enabled, the device remains stuck between Active mode and Shutdown mode. A power-on-reset is needed to recover the device.
<b>Workaround</b>
There is no workaround for this issue.
<b>Resolution</b>
This issue is resolved in revision B devices.



### 3.7 PWR\_E201 – Wakeup From Shutdown Mode Fails at High VDD and Low Temperatures

<b>Description of Errata</b>
The device immediately gets stuck in Shutdown mode when it powers up with VDD greater than 5V and an ambient temperature lower than 0 degrees Celsius.
<b>Affected Conditions / Impacts</b>
With a VDD greater than 5 V at 0 degrees Celsius or below, the inrush current into the startup circuit is too high and causes the device to immediately enter and stay in Shutdown mode, preventing the device from starting up at all.
<b>Workaround</b>
There is no workaround for this issue.
<b>Resolution</b>
This issue is resolved in revision C devices.

### 3.8 VREF\_E201 – RTS Noise Present In Reference Voltage Output

<b>Description of Errata</b>
Certain devices suffer from RTS (random telegraph signal) noise, also known as “popcorn noise” or “burst noise,” in the on-chip voltage reference. This is observed as random, intermittent jumps of the reference between two different voltages.
<b>Affected Conditions / Impacts</b>
Affected devices may exhibit sporadic RTS noise at the output of the on-chip reference source. The noise is typically less than 0.2% of the reference voltage, but may be higher on some devices. Due to the low-frequency, intermittent nature of RTS noise, it is not feasible to screen large device quantities to eliminate the issue at production test.
The on-chip reference source is available internally as an ADC reference, or can be buffered to the VREF pin to be used by the ADC, DAC, or external circuitry. Any circuit using the on-chip reference source will be affected, and the performance of these circuits will be impacted as a result. For example, the full scale input of the ADC is based directly on its voltage reference, and RTS noise at the reference may appear as sudden slope changes or linearity errors in the ADC output. Likewise, RTS noise on the DAC reference will be observed as sudden small changes in the output voltage, proportional to the change on the reference.
There is no direct solution to correct for the RTS noise in the on-chip reference. Systems adversely affected by this issue should select a different reference source. Both the ADC and DAC have the option to use the VDD supply as a reference, as well as an externally-derived reference connected to the VREF pin.
<b>Workaround</b>
There is currently no workaround for this issue.
<b>Resolution</b>
This issue is resolved in revision B devices.

## 4. Revision History

### Revision 0.3

April, 2023

- Added BL\_E201.

### Revision 0.2

August, 2021

- Updated the latest revision to revision C.
- Added CLK\_E201, CORE\_E201, CUR\_E201, POR\_E201, and PWR\_E201.

### Revision 0.1

November, 2020

- Initial release.

# Simplicity Studio

One-click access to MCU and wireless tools, documentation, software, source code libraries & more. Available for Windows, Mac and Linux!



**IoT Portfolio**  
[www.silabs.com/IoT](http://www.silabs.com/IoT)



**SW/HW**  
[www.silabs.com/simplicity](http://www.silabs.com/simplicity)



**Quality**  
[www.silabs.com/quality](http://www.silabs.com/quality)



**Support & Community**  
[www.silabs.com/community](http://www.silabs.com/community)

## Disclaimer

Silicon Labs intends to provide customers with the latest, accurate, and in-depth documentation of all peripherals and modules available for system and software implementers using or intending to use the Silicon Labs products. Characterization data, available modules and peripherals, memory sizes and memory addresses refer to each specific device, and "Typical" parameters provided can and do vary in different applications. Application examples described herein are for illustrative purposes only. Silicon Labs reserves the right to make changes without further notice to the product information, specifications, and descriptions herein, and does not give warranties as to the accuracy or completeness of the included information. Without prior notification, Silicon Labs may update product firmware during the manufacturing process for security or reliability reasons. Such changes will not alter the specifications or the performance of the product. Silicon Labs shall have no liability for the consequences of use of the information supplied in this document. This document does not imply or expressly grant any license to design or fabricate any integrated circuits. The products are not designed or authorized to be used within any FDA Class III devices, applications for which FDA premarket approval is required or Life Support Systems without the specific written consent of Silicon Labs. A "Life Support System" is any product or system intended to support or sustain life and/or health, which, if it fails, can be reasonably expected to result in significant personal injury or death. Silicon Labs products are not designed or authorized for military applications. Silicon Labs products shall under no circumstances be used in weapons of mass destruction including (but not limited to) nuclear, biological or chemical weapons, or missiles capable of delivering such weapons. Silicon Labs disclaims all express and implied warranties and shall not be responsible or liable for any injuries or damages related to use of a Silicon Labs product in such unauthorized applications.

**Note: This content may contain offensive terminology that is now obsolete. Silicon Labs is replacing these terms with inclusive language wherever possible. For more information, visit [www.silabs.com/about-us/inclusive-lexicon-project](http://www.silabs.com/about-us/inclusive-lexicon-project)**

## Trademark Information

Silicon Laboratories Inc.<sup>®</sup>, Silicon Laboratories<sup>®</sup>, Silicon Labs<sup>®</sup>, SiLabs<sup>®</sup> and the Silicon Labs logo<sup>®</sup>, Bluegiga<sup>®</sup>, Bluegiga Logo<sup>®</sup>, EFM<sup>®</sup>, EFM32<sup>®</sup>, EFR, Ember<sup>®</sup>, Energy Micro, Energy Micro logo and combinations thereof, "the world's most energy friendly microcontrollers", Redpine Signals<sup>®</sup>, WiSeConnect, n-Link, ThreadArch<sup>®</sup>, EZLink<sup>®</sup>, EZRadio<sup>®</sup>, EZRadioPRO<sup>®</sup>, Gecko<sup>®</sup>, Gecko OS, Gecko OS Studio, Precision32<sup>®</sup>, Simplicity Studio<sup>®</sup>, Telegesis, the Telegesis Logo<sup>®</sup>, USBXpress<sup>®</sup>, Zentri, the Zentri logo and Zentri DMS, Z-Wave<sup>®</sup>, and others are trademarks or registered trademarks of Silicon Labs. ARM, CORTEX, Cortex-M3 and THUMB are trademarks or registered trademarks of ARM Holdings. Keil is a registered trademark of ARM Limited. Wi-Fi is a registered trademark of the Wi-Fi Alliance. All other products or brand names mentioned herein are trademarks of their respective holders.



Silicon Laboratories Inc.  
400 West Cesar Chavez  
Austin, TX 78701  
USA

[www.silabs.com](http://www.silabs.com)