

User Registration

Register today to create your account on Silabs.com. Your personalized profile allows you to receive technical document updates, new product announcements, "how-to" and design documents, product change notices (PCN) and other valuable content available only to registered users.

<http://www.silabs.com/profile>

Bulletin Date: 7/21/2016	Bulletin Effective Date: 7/21/2016
Title: EM358x/EM359x Revision A3 Errata	
Bulletin Details	
Description: Silicon Labs has issued an errata document for EM358x and EM359x. The errata is available at www.silabs.com .	
Reason: An issue has been discovered with the USB peripheral on the EM38x and EM39x. When using the integrated USB on the EM358x and EM359x, the EM35xx device may fail to enumerate. There is currently no resolution for this issue, but a work around has been provided. Please refer to the errata document for more information.	
Product Identification: EM3582-RT EM3582-RTR EM3582-IRT EM3582-IRTR EM3582-E4T EM3582-E4TR EM3586-RT EM3586-RTR EM3586-IRT EM3586-IRTR EM3586-E4T EM3586-E4TR EM3588-RT EM3588-RTR EM3588-IRT EM3588-IRTR EM3588-E4T EM3588-E4TR EM3592-RT EM3592-RTR EM3596-RT EM3596-RTR EM3598-RT EM3598-RTR	
This change is considered a minor change which does not affect form, fit, function, quality, or reliability. The information is being provided as a customer courtesy.	



Bulletin #1607212

Please contact your local Silicon Labs sales representative with any questions about this notification. A list of Silicon Labs sales representatives may be found at www.silabs.com

Customer Actions Needed:
Review the errata document.