


Revision History

Rev 1.0
Initial Design

Rev 2.0
Antenna retuned
Connector placement error fixed in layout



400 W Cesar Chavez
Austin, TX 78701

SILICON LABS

Title

EFR32 based Lighting Reference Design

Size	Document Number	Rev
B	IST-A0098	2.0

Date:	Wednesday, July 26, 2017	Sheet	1	of	2
-------	--------------------------	-------	---	----	---

