

Bulletin #1509011

User Registration

Register today to create your account on Silabs.com. Your personalized profile allows you to receive technical document updates, new product announcements, "how-to" and design documents, product change notices (PCN) and other valuable content available only to registered users. http://www.silabs.com/profile

Bulletin Date: 9/1/2015	Bulletin Effective Date: 9/1/2015	
Title: EFM8 Errata PCN (BB1, SB1, SB2, UB2)		
Originator: Kafai Leung	Phone: 512-532-5232	Dept: Marketing
Customer Contact: Kathy Haggar	Phone: 512-532-5261	Dept: Sales
Bulletin Details		

Description:

EFM8BB1, EFM8SB1, EFM8SB2, EFM8UB2 Revision B Errata has been updated and are available at www.silabs.com.

Reason:

A "Bootloader Signature Byte" has been added to the EFM8BB1, EFM8SB1, EFM8SB2, EFM8UB2 to support a factory programmed bootloader. More details can be found in the Errata associated with the device family.

- Each device will use the byte immediately before the Lock Byte as a Bootloader Signature Byte to determine if the bootloader is present in flash.
- Systems using the device should not write the Bootloader Signature Byte to 0xA5 to enable normal operation.

Product Identification:

EFM8BB10F2G-A-QFN20

EFM8BB10F2G-A-OFN20R

EFM8BB10F4G-A-QFN20

EFM8BB10F4G-A-QFN20R

EFM8BB10F8G-A-OFN20

EFM8BB10F8G-A-QFN20R

EFM8BB10F8G-A-QSOP24

EFM8BB10F8G-A-QSOP24R

EFM8BB10F8G-A-SOIC16

EFM8BB10F8G-A-SOIC16R

EFM8SB10F2G-A-QFN20

EFM8SB10F2G-A-QFN20R

EFM8SB10F4G-A-QFN20

EFM8SB10F4G-A-QFN20R

EFM8SB10F8G-A-CSP16

EFM8SB10F8G-A-CSP16R

EFM8SB10F8G-A-QFN20

EFM8SB10F8G-A-QFN20R

EFM8SB10F8G-A-QFN24

EFM8SB10F8G-A-QFN24R

EFM8SB10F8G-A-QSOP24

EFM8SB10F8G-A-QSOP24R

EFM8SB20F16G-A-QFN24

EFM8SB20F16G-A-QFN24R



Bulletin #1509011

EFM8SB20F32G-A-QFN24 EFM8SB20F32G-A-QFN24R EFM8SB20F32G-A-QFN32 EFM8SB20F32G-A-QFN32R EFM8SB20F32G-A-QFP32 EFM8SB20F32G-A-QFP32R EFM8SB20F64G-A-QFN24 EFM8SB20F64G-A-QFN24R EFM8SB20F64G-A-QFN32 EFM8SB20F64G-A-QFN32R EFM8SB20F64G-A-QFP32 EFM8SB20F64G-A-QFP32R EFM8UB20F32G-A-QFN32 EFM8UB20F32G-A-QFN32R EFM8UB20F32G-A-QFP32 EFM8UB20F32G-A-QFP32R EFM8UB20F32G-A-QFP48 EFM8UB20F32G-A-QFP48R EFM8UB20F64G-A-QFN32 EFM8UB20F64G-A-QFN32R EFM8UB20F64G-A-QFP32 EFM8UB20F64G-A-QFP32R EFM8UB20F64G-A-QFP48 EFM8UB20F64G-A-QFP48R This change is considered a minor change which does not affect form, fit, function, quality, or

reliability. The information is being provided as a customer courtesy.

Please contact your local Silicon Labs sales representative with any questions about this notification. A list of Silicon Labs sales representatives may be found at www.silabs.com

Customer Actions Needed:

Care should be taken not to write the value 0xA5 to the "Bootloader Signature Byte" location. The value 0xA5 will be used to activate the pre-programmed bootloader.